MyChron5S Release history

Version	Date	Change/additions
02.40.75	Sep, 21st 2023	▪ Fixed alarm configuration setup when temperature/s is/are set in manual mode ▪ Fixed freezing cases at startup **External modules** No changes
02.40.63	Jun, 12th 2023	▪ Fixed lap manager in OPTICAL/MAGNETIC beacon manual mode (EU systems only) when GPS Assistance is enabled ▪ Fixed lateral grip acquisition for OVAL mode **External modules** No changes
02.40.53	Feb, 7th 2023	▪ Minor improvements **External modules** No changes
02.40.52	Feb, 1st 2023	For MYC5S serial number greater than 83040000 only: ▪ Improved temperatures acquisition ▪ Added CVT drive mode ▪ Improved optical lap acquisition **External modules** No changes
02.40.40	Nov, 23rd 2022	▪ Added predictive reference lap management **External modules** No changes

MyChron5S Release history

Version	Date	Change/additions
02.40.28	Sep, 19th 2022	▪ Fix of thermoresistance analog measure (REV01 boards)
		External modules
		No changes
02.40.13	Jun, 24th 2022	▪ Fixed bug on data recall review, in some cases the max speed value was wrong
		External modules
		No changes
02.40.00	May, 17th 2022	▪ SmartyCam 3 Sport support
		External modules
		No changes
02.38.18	Mar, 29th 2022	▪ New boards (MYC63 and MYC64) support
		External modules
		No changes
02.36.94	Dec, 10th 2021	▪ Fixed bug on Daylight Saving Time application in Southern Hemisphere
		▪ Fixed Mychron Expansion channels configuration in recording file: in some cases the channels were missing in RS3 Analysis visualization
		External modules
		No changes
02.36.80	Sep, 14th 2021	▪ Fixed bug that caused no laps tests
		External modules
		No changes

MyChron5S Release history

Version	Date	Change/additions
02.36.78	Sep, 10th 2021	▪ Fixed shut down procedure that in some devices didn't working **External modules** No changes
02.36.55	Jun, 17th 2021	▪ Improved GPS switch ON procedure to prevent the "GPS ERROR" issue **External modules** No changes
02.36.32	Apr 27th 2021	▪ Improved GPS data time synchronization ▪ Fixed channels acquisition name that caused issue with Race Studio Analysis mathematical channels **External modules** No changes
02.36.21	Apr 9th 2021	▪ Fixed missed system switch on events ▪ Fixed bad display reset events **External modules** No changes
02.36.19	Apr 2nd 2021	▪ Improved GPS inizialization ▪ Fixed unexpected system cycle of restart when the internal battery is charged and the external battery is connected ▪ Fixed temperature channels visualization in custom page (sometimes missing, blank value when digits number was greater than 3) **External modules** No changes

AiM Tech Srl - Via Cavalcanti, 8 20063 Cernusco sul Naviglio, Milan, Italy | Tel. +39.02.9290571 | info@aim-sportline.com

aim-sportline.com

MyChron5S Release history

Version	Date	Change/additions
02.34.43	Jan 19th 2021	■ Fixed temperatures on display visualization when two sensors with the same function are set (e.g. EGT1/EGT2) ■ Fixed selected track name visualization on display ■ Improved RPM measure calculation ■ Improved display management in case of electro-magnetic noise situations **External modules** No changes
02.34.34	Nov 13th 2020	■ Fixed bug that could cause half RPM value ■ Fixed temperature max/min values in resume lap page and in data recall **External modules** No changes
02.34.24	Oct 14th 2020	■ Improved GPS status visualization in GPS track page ■ Added missing "Auto" mode in backlight menu ■ Added "Rec with GPS speed" in debug mode menu ■ Fixed bug on RPM acquisition that caused RPM calculated as half of the true value ■ Fixed track autolearning enable/disable in GPS track page ■ Fixed alarms menu setup ■ Fixed unit measure conversion of temperatures in data recall pages ■ Fixed data recall for Oval Race mode **External modules** No changes