

May, 16th 2024

Page 1

MXS Strada Release history

Date

Version

Change/additions

01.32.34

5

May, 16th 2024 Fixed bug that could cause GPS data lost

External modules No changes



May, 16th 2024

Page 2

Version	Date	Change/additions
01.32.22	Mar, 15th 2023	■ GPS09C support
		External modules
		No changes
01.32.16	Jul, 27th 2022	New expansions boards (GSDASH2, Shiftlight_B) support
		External modules
		02.40.10 Shiftlight Module B
		02.40.21 GSDASH2
		01.32.16 GSDASH
01.32.08	Jun, 7th 2022	Fixed GPS data sampling from GPS CAN devices (GPS08/GPS09)
		External modules
		No changes
01.32.00	May, 17th 2022	SmartyCam 3 Sport support
		External modules
		No changes
01.30.44	May, 2nd 2022	Fixed digital speed parameters from RS3 configuration setup
		External modules
		No changes
01.30.38	Feb, 18th 2022	Added GPS09B device support
01100100	,	External modules
		02.38.03 GPS09B
		- 02.30.03 GF309b
01.30.30	Aug, 6th 2021	Fixed bad GPS data synchronization (that caused shorter lap times and GPS speed acquisition)
		External modules
		02.36.64 GPS09 Module
01.30.06	Nov, 25th 2020	Added GPS09 support
01.30.00	1000, 2011 2020	External modules
		35.65 GPS Module: Fix Masterclock received from master that caused bad values in GPS data timestamp



May, 16th 2024

Page 3

Version	Date	Change/additions
01.30.00	Jun, 9th 2020	Race Simulators handling
		Added Hour/Date info from GPS tracks
		Added reference speed used to calculate odometers
		Improved k-line handling
		External modules
		No changes
01.28.20	Dec, 4th 2019	Improved setting of LEDs brightness
		Fixed issue on CAN bus off handling of ECU CAN line
		Improved synchronization between data from GPS and local data acquisition
		External modules
		35.64 GPS Module
		Improved synchronization between data from GPS and local data acquisition
01.28.10	Jul, 5th 2019	■ Fixed bug in Channel Expansion/TCHub firmware that caused blinking in Race Studio 3 Live Measures
		External modules
		40.63 Channel Expansion/TC Hub
		Fixed bug that caused blinking in Race Studio 3 Live Measures
01.28.08	Jun, 12th 2019	Fixed CAN protocols with multiplex frames
		External modules
		40.62 Channel Expansion/TC Hub
		35.61 GPS Module
01.28.03	Feb, 12th 2019	Fixed display artifacts in measures value cleaning
		External modules
		01.26.49 GS-Dash
		 Measures timeout improved Spansion support
		 Spansion support Fix data recall synchronization issue
		02.26.51 Shift Light Module
		Fixed issues with some ECUs
		No changes for the other modules



May, 16th 2024

MXS Strada Release history

Page 4

Version	Date	Change/additions
01.26.46	Dec, 5th 2018	Added management of Shift Light Module
		Added the support for auto brightness levels configuration (day brightness level, night brightness level and threshold are now fully configurable)
		External modules
		No changes
01.26.38	Oct, 5th 2018	Added possibility to force channels in Online
		Fixed bug on Digital output priority handling
		External modules
		No changes
01.26.20	Ann 12th 2010	
01.26.28	Apr, 12th 2018	No changes
01.26.25	Jan 11th 2018	Fixed bug when the Start Data Recording standard condition is configured: in some conditions it caused not recorded data
		Fixed bug in volume sensors with gallons unit measure
		External modules
		35.58 GPS Module
		25.47 Lambda
		40.61 Channel Expansion/TC Hub
		70.03 Remote buttons interface
01.26.24	Nov 14th 2017	No changes
01.26.23	Oct 24th 2017	Support for CAN builder ID mask feature
		Consumed fuel channel
		Fix: Pulse per wheel revolution setting not working for Speed1 or Speed2 digital inputs
		Fix: wrong order of operands in bias math channel
		External modules
		35.58 GPS Module
		25.46 Lambda
		40.60 Channel Expansion/TC Hub
		70.03 Remote buttons interface



May, 16th 2024

Page 5

Version	Date	Change/additions
01.26.14	Jul 7th 2017	Improved CAN management: more reliability in firmup and configuration transmission
		External modules
		35.58 GPS Module
		25.46 Lambda
		40.60 Channel Expansion/TC Hub: minor bugs fixed
		70.03 Remote buttons interface
01.26.08	Jun 20th 2017	No changes
		External modules
		35.58 GPS Module
		25.46 Lambda
		40.60 Channel Expansion/TC Hub
		70.01 Remote buttons interface
01.24.54	May 19th 2017	Includes firmware GPS v 35.58.00 that fixes data synchronization with SmartyCam HD
01.24.34	May 19th 2017	External modules
		35.58 GPS Module
		25.46 Lambda
		 40.60 Channel Expansion/TC Hub: minor bugs fixed
		70.01 Remote buttons interface
01.24.52	May 18th 2017	Added support for new display configuration (RaceStudio3 v 3.15.00 required)
		External modules
		35.56 GPS Module
		25.46 Lambda
		40.60 Channel Expansion/TC Hub: minor bugs fixed
		70.01 Remote buttons interface
01.24.14	May 24th 2017	Et al barrente en esta de la construcción de la construcción
01.24.14	Mar 24th 2017	Fixed bug that caused no data from channels with hysteresis
		External modules
		35.56 GPS Module
		25.46 Lambda
		40.56 Channel Expansion/TC Hub
		70.01 Remote buttons interface



May, 16th 2024

MXS Strada Release history

Page 6

Version	Date	Change/additions
01 24 12	Max 24th 2017	
01.24.13	Mar 24th 2017	Improved accelerometer support: better filtering and uniform sign convention on various devices
		 Fixed occasional spikes on accelerometer channels
		External modules
		35.56 GPS Module
		25.46 Lambda
		40.56 Channel Expansion/TC Hub
		70.01 Remote buttons interface
01.24.00	Jan 26th 2017	Fixed issue that caused CAN network malfunction when remote button device is in the network
		External modules
		35.56 GPS Module
		25.46 Lambda
		40.56 Channel Expansion/TC Hub
		70.01 Remote buttons interface
01.22.99	Jan 19th 2017	Added management of GPS position accuracy measure for display and CAN output
		Fixed bug in "Backlight" menu voice (icon missed)
		External modules
		35.56 GPS Module
		25.46 Lambda
		40.56 Channel Expansion/TC Hub
		70.01 Remote buttons interface
01.22.94	Dec 5th 2016	No changes
		External modules
		35.56 GPS Module
		25.46 Lambda: fixed bug that caused shifted lambda samples
		40.56 Channel Expansion/TC Hub
		70.01 Remote buttons interface



May, 16th 2024

Page 7

Version	Date	Change/additions
01.22.92	Nov 29th 2016	Minor improvements
		External modules
		35.56 GPS Module: improvements in GPS measurements available to SmartyCam overlay
		25.44 Lambda
		40.56 Channel Expansion/TC Hub
		70.01 Remote buttons interface
01.22.86	Nov 15th 2016	Added IRM CAN LAP support
01.22.00	100 15112010	
		Warning: this firmware release requires Race Studio 3 ver. 3.10.10 or higher.
		External modules
		35.54 GPS Module: improved satellites fix
		25.44 Lambda: added keep alive support
		40.56 Channel Expansion/TC Hub
		70.01 Remote buttons interface
01 22 02	Oct 11th 2016	
01.22.82	Oct 11th 2016	Speed up USB transfer
		 Speed up display pages loading at the startup
		Fixed bug in GPS lap management that in some cases caused loss of laps detected
		Warning: this firmware release requires Race Studio 3 ver. 3.10.10 or higher.
		External modules
		35.50 GPS Module
		25.42 Lambda
		40.56 Channel Expansion/TC Hub: improved analogic channels acquisition
		70.01 Remote buttons interface
01.22.74	Sep 15th 2016	Fixed alarms functionality based on acquisition channels under encryption
		Fixed message alarms that sometimes were partially or totally erased
		Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher.
		External modules
		35.50 GPS Module
		25.42 Lambda
		40.55 Channel Expansion/TC Hub
		70.01 Remote buttons interface



May, 16th 2024

MXS Strada Release history Page 8 Version Date Change/additions Fixed: clear alarm by remote buttons 01.22.60 Jul 25th 2016 Fixed: alarm hysteresis condition Minor bugfixes and improvements Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher. **External modules 35.50** GPS Module **25.42** Lambda 40.55 Channel Expansion/TC Hub **70.01** Remote buttons interface Jun 17th 2016 Fixed display issue when 8 pages are configured 01.22.16 Fixed bug on Shift Light management Minor improvements Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher. **External modules 35.50** GPS Module **25.42** Lambda 40.55 Channel Expansion/TC Hub **70.01** Remote buttons interface 01.22.14 Jun 10th 2016 New track management, compatible with the MyChron5 one Test data recall Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher. **External modules 35.50** GPS Module **25.42** Lambd 40.55 Channel Expansion/TC Hub **70.01** Remote buttons interface