



## MXK10 5th gen Release history

Version	Date	Change/additions
<b>02.28.64</b>	May, 12th 2023	<ul style="list-style-type: none"><li>▪ Support for GPS09c</li><li>▪ Fixed partial odometer menu</li><li>▪ Fixed traction control settings from menu</li></ul> <b>External modules</b> No changes
<b>02.28.58</b>	Oct, 3rd 2022	<ul style="list-style-type: none"><li>▪ Improved startup speed to avoid KDS Error 39 in ECU</li><li>▪ NOTE: error happens for devices shipped from June 2022 onwards</li></ul> <b>External modules</b> No changes
<b>02.28.49</b>	Feb, 18th 2022	<ul style="list-style-type: none"><li>▪ Fixed GPS histogram visualization</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>02.36.64</b> GPS09: Improved GPS data synchronization</li><li>▪ <b>02.38.03</b> GPS09B</li></ul>
<b>02.28.43</b>	Nov, 23rd 2021	<ul style="list-style-type: none"><li>▪ Fixed OBDII interaction that avoided the use of external OBDII interfaces</li><li>▪ Fixed data recall file creation bug</li></ul> <b>External modules</b> No changes
<b>02.28.36</b>	Feb, 12th 2021	<ul style="list-style-type: none"><li>▪ Added GPS09 support</li></ul> <b>External modules</b> <b>35.65</b> GPS Module: Fix Masterclock received from master that caused bad values in GPS data timestamp
<b>02.28.33</b>	Oct, 6th 2020	<ul style="list-style-type: none"><li>▪ Added fuel consumption</li><li>▪ Improved diagnostics</li><li>▪ Fixed KTRC bug</li><li>▪ Fixed KIBS menu</li></ul> <b>External modules</b> No changes

## MXK10 5th gen Release history

Page 2

Version	Date	Change/additions
<b>02.28.26</b>	Apr, 30th 2020	<ul style="list-style-type: none"><li>▪ Add launch control support for remapped ECUs (i.e. Woolich)</li><li>▪ Add diagnostics support through LEDs and dedicated menu</li><li>▪ Add speed multiplier feature (i.e. to compensate different wheel size)</li><li>▪ Add modules menu to set if KECS and KIBS modules are installed</li></ul> <b>External modules</b> No changes
<b>02.28.01</b>	Sep, 27th 2019	<ul style="list-style-type: none"><li>▪ Fixed a bug in setting "POWER MODE" in "VEHICLE SETTINGS" menu, introduced in the 02.27.92 version</li></ul> <b>External modules</b> No changes
<b>02.27.92</b>	Sep, 18th 2019	Note: this release has been removed and replaced by 02.28.01 version. <ul style="list-style-type: none"><li>▪ Increased frequency (50Hz) for ECU protocol channels SHIFTER and TPS</li><li>▪ Improved battery voltage readings</li></ul> <b>External modules</b> No changes
<b>02.27.88</b>	Jul, 29th 2019	<ul style="list-style-type: none"><li>▪ Laptime type (Rolling, Static, Predictive or +/- Best) choice from Display menu</li></ul> <b>External modules</b> No changes
<b>02.27.83</b>	Jul, 17th 2019	<ul style="list-style-type: none"><li>▪ Configurable shift lights (by software)</li><li>▪ Analog/digital page change only from a dedicated command in the menu</li><li>▪ TC and Power Select even when the bike is in movement (only if the Track Kit is installed)</li><li>▪ Layout choice between Black or White, and possibility to automatically select them in dependence of the light level</li><li>▪ Improved Light Sensor management</li></ul> <b>External modules</b> No changes



## MXK10 5th gen Release history

Version	Date	Change/additions
<b>02.27.79</b>	Jun, 9th 2019	<p>First official update</p> <ul style="list-style-type: none"><li>▪ ECU/GPS speed selection from menu</li><li>▪ Introduced power mode management in riding mode for Racing Kit ECU</li><li>▪ New page selection management via menu</li><li>▪ New menus (previews, kecs and gps info)</li><li>▪ Ect and battery alarms configurable from device</li></ul> <p><b>External modules</b></p> <p>No changes</p>