



<b>CUSTOMER DOCUMENTATION</b>	<b>September 1<sup>st</sup> 2005</b>	<b>FIRMWARE</b>	<b>MyChron 3 660</b>
<b>Firmware Release history: MyChron 3 660 "Dragster Junior"</b>			<b>Release history</b>

**September 1<sup>st</sup> 2005**

**Firmup4\_DRAG\_050901.exe**

<b>Logger</b>	<b>Version</b>	<b>Changes – Additions</b>
MyChron 3 660	4.28	<ul style="list-style-type: none"><li>• No Firmware changes since last version.</li><li>• After firmware upgrading display now shows Firmware version 4.28, while before it correctly upgraded the logger, but wrongly showed firmware version 4.27.</li></ul>

**July 21<sup>st</sup> 2005**

**Firmup4\_DRAG\_050721.exe**

<b>Logger</b>	<b>Version</b>	<b>Changes – Additions</b>
MyChron 3 660	4.28	<ul style="list-style-type: none"><li>• Demo mode re-starts automatically.</li></ul>

**March 11<sup>th</sup> 2005**

**Firmup4\_DRAG\_050311.exe**

<b>Logger</b>	<b>Version</b>	<b>Changes – Additions</b>
MyChron 3 660	4.27	<ul style="list-style-type: none"><li>• Fixed bug that could cause memorization problems</li></ul>

**January 24<sup>th</sup> 2005**

**Firmup4\_DRAG\_050124.exe**

<b>Logger</b>	<b>Version</b>	<b>Changes – Additions</b>
MyChron 3 660	4.26	<ul style="list-style-type: none"><li>• From this firmware version onward it is possible to recover incomplete booter writings.</li></ul>

**December 1<sup>st</sup> 2004**

**Firmup4\_DRAG\_041201.exe**

<b>Logger</b>	<b>Version</b>	<b>Changes - Additions</b>
MyChron 3 660	4.24	<ul style="list-style-type: none"><li>• No firmware changes since last release</li><li>• Fixed bug: after running firmup, at the end, the system gave erroneously a warning message.</li></ul>

**October 27<sup>th</sup> 2004**

**Firmup4\_DRAG\_040120.exe**

<b>Logger</b>	<b>Version</b>	<b>Changes - Additions</b>
MyChron 3 660	4.24	<ul style="list-style-type: none"><li>• No firmware changes since last release</li><li>• Support for new USB drivers (10.01) made official; still supports old USB drivers (since Race Studio 2.17.xx)</li></ul>

**January 20<sup>th</sup> 2004**

**Firmup\_DRAG\_040120.exe**

<b>Logger</b>	<b>Version</b>	<b>Changes - Additions</b>
MyChron 3 660	4.24	<ul style="list-style-type: none"><li>• Added support for new display supplier</li></ul>



---

January 13<sup>th</sup> 2004

**Firmup\_DRAG\_040112.exe**

---

Logger	Version	Changes - Additions
MyChron 3 660	4.23	<ul style="list-style-type: none"><li>Fixed memory management bug: in some runs the data were put to 0 for approx. 3-4 seconds</li><li>Fixed visualization bug: some dates (months or days) were not correctly displayed</li><li>Fixed bug: the Drive-gear and Driven-gear value could decrease under the minimum value</li><li>New feature: once finished a run, the logger restarts sampling only if speed value goes to 0</li></ul>

---

December 2<sup>nd</sup>. 2003

**Firmup\_DRAG\_031202.exe**

---

Logger	Version	Changes - Additions
MyChron 3 660	4.21	<ul style="list-style-type: none"><li>No firmware changes – More robust FIRMUP file architecture (Version 2.01)</li></ul>

---

November 13<sup>th</sup>. 2003

**Firmup\_M3DRAG660\_031113.exe**

---

Logger	Version	Changes - Additions
MyChron 3 660	4.21	<ul style="list-style-type: none"><li>Deleted “Speed” display page</li></ul>

---

November 12<sup>th</sup>. 2003

**Firmup\_M3DRAG660\_031112.exe**

---

Logger	Version	Changes - Additions
MyChron 3 660	4.20	<ul style="list-style-type: none"><li>Fixed bug with “Set date and time”</li><li>Added “Run Counter” feature</li><li>If the speed channel is not available, the gauge stores the input channels’ maximum values</li><li>Modified “Check mode” timeout to 10 seconds.</li></ul>

---

November 6<sup>th</sup>. 2003

**Firmup\_M3DRAG660\_031106.exe**

---

Logger	Version	Changes - Additions
MyChron 3 660	4.19	<ul style="list-style-type: none"><li>Fixed bug in Replay mode</li></ul>