



CUSTOMER DOCUMENTATION	March 22nd 2005	FIRMWARE	EVO 3
Firmware Release history: EVO 3			Release history

March 22nd 2005 **Firmup4_EVO3_050322.exe**

Logger	Version	Changes - Additions
EVO 3	1.41	<ul style="list-style-type: none">• Fixed PT 100 reading and conversion for Channels 9-13

January 31st 2005 **Firmup4_EVO3_050131.exe**

Logger	Version	Changes – Additions
EVO 3	1.40	<ul style="list-style-type: none">• Added possibility to update Booter from firmware• Booter writing made more robust

December 10th. 2004 **Firmup4_EVO3_041210.exe**

Logger	Version	Changes – Additions
EVO 3	1.39	<ul style="list-style-type: none">• No firmware changes since last release• Firmware made bi-lingual: Italian and English

October 27th. 2004 **Firmup4_EVO3_040325.exe**

Logger	Version	Changes – Additions
EVO 3	1.39	<ul style="list-style-type: none">• No firmware changes since last release• Support for new USB drivers (10.01) made official; still supports old USB drivers (since Race Studio 2.17.xx)

March 25th. 2004 **Firmup_EVO3_040325.exe**

Logger	Version	Changes – Additions
EVO 3	1.39	<ul style="list-style-type: none">• Read Potentiometer counts also when the Voltage Reference is not good.

December 2nd. 2003 **Firmup_EVO3_031202.exe**

Logger	Version	Changes – Additions
EVO 3	1.38	<ul style="list-style-type: none">• No firmware changes – More robust FIRMUP file architecture (Version 2.01)

November 6th. 2003 **Firmup_EVO3_031106.exe**

Logger	Version	Changes – Additions
EVO 3	1.38	<ul style="list-style-type: none">• Added “Revolution Speed” to sensors’ database



June 27th. 2003

FirmUpAll_030627.exe

Logger	Version	Changes – Additions
EVO 3	1.37	<ul style="list-style-type: none">PT100 thermoresistance added to sensors' database (Race Studio 2.14.14 required)

May 8th. 2003

FirmUpAll_030508.exe

Logger	Version	Changes - Additions
EVO 3	1.36	<ul style="list-style-type: none">Gear potentiometer fixed for M3Dash - RPM start acquisition

November 11th. 2002

FirmUpAll_021114.exe

Logger	Version	Changes - Additions
EVO 3	1.35	<ul style="list-style-type: none">Fixed the Checksum error for certain particular situationsAt power up the Reset command is no more txd, to avoid last data erasing on the display. The data are now erased only at download.

June 28th. 2002

FirmUpAll_020628.exe

Logger	Version	Changes - Additions
EVO 3	1.34	<ul style="list-style-type: none">Evo3 Can communicate with M3 Dash for Gear and Custom sensor

June 13th. 2002

FirmUpAll_020613.exe

Logger	Version	Changes - Additions
EVO 3	1.33	<ul style="list-style-type: none">Send f.s. RPM to the Dash

June 6th. 2002

FirmUpAll_020606.exe

Logger	Version	Changes - Additions
EVO 3	1.32	<ul style="list-style-type: none">Deton., Rotation, Speed from ABS (Clio), Code for DCH11/MYC3PG

May 31st. 2002

FirmUpAll_020531.exe

Logger	Version	Changes - Additions
EVO 3	1.31	<ul style="list-style-type: none">Added EVO 3 4Channels - 8Mb

May 30th. 2002

FirmUpAll_020530.exe

Logger	Version	Changes - Additions
EVO 3	1.30	<ul style="list-style-type: none">First version released with FirmUpAll_yymmdd.exe