



CUSTOMER DOCUMENTATION	December 10th 2007	FIRMWARE	DaVid Release history
Firmware Release history: DaVid Video System			

December 10th 2007**Firmup_DAVID_071210.exe**

Logger	Version	Changes - Additions
DaVid StandAlone	17.08	<ul style="list-style-type: none">Improved Speed channel management on TG Dash and MyChron 3 displays

April 5th 2006**Firmup_DAVID_060405.exe**

Logger	Version	Changes - Additions
DaVid StandAlone	17.07	<ul style="list-style-type: none">Changed direction of accelerometers visualization on display

July 11th 2005**Firmup_DAVID_050711.exe**

Logger	Version	Changes - Additions
DaVid StandAlone	17.06	<ul style="list-style-type: none">Added 1/5 RPM Multiply factorModified "Video Numeric Objects" managementModified "Free time" management in lap graphic object: last lap time is shown for 5 secondsImproved gear compute:<ul style="list-style-type: none">- computing needed time is 1/10 than before- corrected compute in some particular cases like when recording lap and recognition of a gear less than declared (like, for instance when starting engaging second gear for compute lap)Added support for Video Configuration Reading for David Slave included in Race Studio 2.20.13Corrected Accelerometers managementClear data message displayed on MyChron 3 Dash when made and clear data message sent to MyChron3 Dash at DaVid switch on if DaVid memory is empty.Fixed bug: corrected speed 1 and / or Speed 2 management for ABS sensor

May 11th 2005**Firmup_VIDEOSYSTEM_050511.exe**

Logger	Version	Changes – Additions
DaVid	17.05	<ul style="list-style-type: none">Calculated gear available for both RPM/Speed or ECUFixed bug on wrong channel 5 management with calculated gearDisplay warning messages concerning configuration errors and calibration procedure steps.Improved reference speed managementAdded possibility of firmware upgrade for MyChron 3 Slave (version 10.08)

April 11th 2005**Firmup_VIDEOSYSTEM_050411.exe**

Logger	Version	Changes – Additions
DaVid	17.04	<ul style="list-style-type: none">Corrected ECU channel configuration for System Visor

March 31st 2005

Firmup_VIDEOSYSTEM_050331.exe

Logger	Version	Changes – Additions
DaVid	17.03	<ul style="list-style-type: none">• Added MyChron 3 Dash 15.01 firmware version support• Fixed lap visualization (Test and split number)

March 11th 2005

Firmup_VIDEOSYSTEM_050311.exe

Logger	Version	Changes – Additions
DaVid	17.01	<ul style="list-style-type: none">• First official Firmup version