





SW4 Release history

Page 1

Version	Date	Change/additions
02.42.32	Apr, 11th 2025	■ Improved ACC3 configuration/calibration
		■ Introduced restore state for toggle and multistatus button
		■ Fixed "Integer with sign bit" management
		■ Increased max CAN output frame to 24
		External modules
		02.42.30 ACC3: fixed bug in calibration procedure
02.42.17	Oct, 10th 2024	■ K6/K8/K15 Keypad support
		External modules
		No changes
02.42.06	Jun, 17th 2024	■ LCU1S support
		External modules
		No changes
02.42.01	Apr, 18th 2024	■ ACC2 and ACC2 Open support
		External modules
		02.40.73 ACC
		02.40.95 ACC2
		02.40.95 GPS09c/GPS09c Open/GPS09c Pro Open
		■ 02.40.85 GPS09 ■ 02.40.72 GPS09B
		1.32.30 GS-Dash
02.40.77	Oct, 11th 2023	■ Improved AiM CAN NET
		External modules
		25.49 LCU-One CAN (improved warm up handling)
		■ 01.32.28 MMOD Strada Logger (fix Net table in download data)
		02.40.73 ACC (fix sample time bug caused no recorded data)







SW4 Release history

Page 2

Version	Date	Change/additions
02.40.53	Feb, 7th 2023	■ GPS09C support External modules No changes
02.40.40	Nov, 23rd 2022	 Added predictive reference lap management External modules No changes
02.40.15	Jul, 8th 2022	 Buttons and paddle shifters support on Sim wheels External modules No changes
02.40.00	May, 17th 2022	■ SmartyCam 3 Sport support External modules No changes
02.36.86	Oct, 5th 2021	 New configuration support. Firmware needed using Race Studio 3 3.38.03 "Left2", "Left3", "Right2" and "Right3" buttons used to navigate the menu